Work Order ID 100237 \*100237\* Page 1 Monday, April 22, 2013 10:41:21 AM Item ID: D3265-5 Accept \*N900040100\* Setup Start **Revision ID:** Stop Item Name: Rib \*4\* Start Qty: 4.00 **Start Date:** 4/22/2013 **Cust Item ID:** Required Date: 4/26/2013 Req'd Qty: 4.00 **Customer:** Reference: Run Start Date: 3-04-22 Tooling: **Approvals:** Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ **Tool ID** Tool # Plan Accept Reject Reject Insp. Work Center ID Description Code Qty **Qty** Number Stamp **Run Hours Draw Nbr Revision Nbr** D3265 Е 100 0.00 Large Fab \*100\* 0.00 Large Fab Memo Large Fab 1- cut D3265-5 rib as per dwg 2- remove identification markings 3- deburr 110 QC5- Inspect part completeness to step on W/O 0.00 \*110\* QC 0.00 Memo Quality Control Cp(13.4.22 Identify as per dwg & Stock Location: W# 120 \*120\* Packaging Memo

Packaging

NCR:	Yes	1	No
NCA.	162	,	INU

DQA: \_\_\_\_\_ Date: \_\_\_

NCR: Y	es / No				WORK ORDER NON-C	CONFO	PRM	IANCE / UPI	DATE					
										QA Closed:	Date:			
Work Orde	r:				DISPOSITION		AGAINST DEPARTMENT/PROCESS							
					Rework	1 I	S	Skid-tube	Crosstube		Water Jet	Engineering		
Part N	lo				Scrap	] [	M	1achining	Small Fab	Pro	d. Eng. Coor.	Quality		
					Use-as-is	Th		oforming	Finishing	Rec/Sto	re/Packaging	Other		
NCR N	lo				Work Order Update	! <b> </b>	L	arge Fab	Composite	Ţ	Supplier	] []		
Root				Descri	ption of work order update	Initia	ıl	Act	ion	Sign &				
Cause	Date	Step	Qty		or Non-conformance	Chief E	ng	Descr	ription	Date	Verification	QC Inspector		
Doc/Data														
Equip/Tooling						ļ								
Operator														
Material [														
Setup														
Other														
Process										٠				
Supplier														
Training				,										
Unapproved		1				<u> </u>				<u> </u>				
					<del> </del>	AULT CA	ATEG	ORY						
Landir	ng Gear				General				_	_	-	7		
	Bending			_	Bend	Grai				Ovalized	<u> </u>	Pressure/Forced		
	Centre N	ot Conce	ntric to (	o/s	BOM/Route	$\rightarrow$	dwar		_	Over/Under		Temperature/Cure		
<b>8</b> ,3	Cracks				Broken/Damaged	Insp	ectio	on Incomplete		Part Incorre	<del>-</del>	Weld		
٠ - ١	Crushed/	'Crimped		_	Burrs			ons Incomplete/l	Jnclear	Part Lost/Mi	ssing	Wrong Stock Pulled		
	Cuffs				Contamination	$\vdash$		nance		Part Moved				
	Heat Treat Countersink					Misl	labele	ed		Positioned V	_	<b>-</b>		
	Inspection Strip in Tube Cut Too Short				<b>-</b>	Misr			Ĺ	Power Loss/	Surge	Other		
Ripples in Bend					Drill Holes	Offs				<del></del>				
	Torque V	Vaves in I	Extrusio	n L	Drawing	Out	of Ca	alibration		<del>, , , , , , , , , , , , , , , , , , , </del>		,		
	Turning S	Sequence			Finish ·	Out	Out of Sequence							
	Wave/Tv	vist in Tul	be		Folio	Out	side (	Dimensions						

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Orde Monday, April 2				*100	1237*							Page 2
Item ID: Revision ID: Item Name:	D3265-5			Accept	*N900	)* 5	Setup S	Start Stop	r va	S1* S2*		
Start Date: Required Date: Reference:	4/22/2013 4/26/2013	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item ! Customer:	D:						
Approvals: Process Plan: QC:			Date:		D	1		Start Stop	*N *N	R1* R2*		
Sequence ID/ Work Center II 130 *130*	)	Operation Description QC21- Final Inspection -	Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty		Reject lumber	Insp. Stamp
QC Quality Control		Memo		0.00							. 1	

Pl 13-04-23

												DQA	: Date:		
NCR: Y	Yes	/ No				WORK	ORDER NON-C	CON	<b>VFORI</b>	MANCE / U	PDATE		<del></del>	•	
						,						QA Closed	: Date:		
Work Orde	er.					C	DISPOSITION	AGAINST DEPARTMENT/PROCESS							
Work orac	-				<del></del>	Rework Skid-tube			Crosstube	7	Engineering				
Part No.						Scrap	1	1	Machining	Small Fab	Pr	Water Jet od. Eng. Coor.	Quality		
							Use-as-is	Thermoforming Finishing				ore/Packaging	Other		
NCR N	No.					Worl	k Order Update	Large Fab Composite Supplier					Supplier		
		-												·	
Root							ork order update	1	nitial	1	ction	Sign &			
Cause		Date	Step	Qty		or Non-con	formance	Ch	ief Eng	Des	cription	Date	Verification	QC Inspector	
Doc/Data				·		•									
Equip/Tooling	Ш	.				:							1		
Operator	Ш														
Material										·					
Setup	Ш	. *													
Other	Ш		<u> </u>												
Process	Ш		1					1							
Supplier	Ш			•											
Training	Ш												-		
Unapproved	Ш		<u></u>			<u>-</u>									
						<u> </u>		AUL	T CATE	GORY	•				
Landi	ng G	ear			<u> </u>	4	General		ì		_	<del></del> 1	<del></del>	7	
	{	Bending				Bend		1 1	Grain	•		Ovalized		Pressure/Forced	

Mislabeled Positioned Wrong Heat Treat Countersink Misread Power Loss/Surge Other Inspection Strip in Tube Cut Too Short Ripples in Bend Drill Holes Offset Out of Calibration Torque Waves in Extrusion Drawing Out of Sequence Turning Sequence Finish Folio Outside Dimensions Wave/Twist in Tube

Hardware

Maintenance

Inspection Incomplete

Instructions Incomplete/Unclear

Temperature/Cure

Wrong Stock Pulled

Weld

Over/Under tolerance

Part Incorrect
Part Lost/Missing

Part Moved

Cracks

Cuffs

Crushed/Crimped

Centre Not Concentric to O/S

BOM/Route

Contamination

Burrs

Broken/Damaged

**Picklist Print** Page 1 Monday, April 22, 2013 10:41:26 AM Work Order ID: 100237 \*100237\* D3265-5 \*D3265-5\* Parent Item: Parent Item Name: Rib **Start Date:** 4/22/2013 **Required Date: 4/26/2013** Start Qty: 4.00 Required Qty: 4.00 Comments: IPP REV:A 12.07.26 AS PER DWG REV.D DD VERF:EC Component Item ID/ Bin Primary Route Unit of Qty on Qty per Kit Total Replacement Mfg/ Last Qty Date Status Item Name Item ID Item Location Location Seq ID Measure Hand Issued Issued Purch Qty 1,127.990 2.2708 M304TS0.750W.065 Purchased No 100 9.557895 \*\* \*M304TS0 750W 065\* 304 SQ Tube .75x.75x.065W Location Loc Qty Loc Code

436.4116

436.4116

691.579

691.579

MAT017

WA006

124069

125068

											DQA:	Dat	e:
NCR:	⁄es	/ No				WORK ORDER NON-C	100	NFORI	MANCE / UP	DATE	QA Closed:	Dat	a·
		-								-	QA Closed.	Dat	С.
Work Orde	or-					DISPOSITION			AGAINST DE	PARTMENT	/PROCESS		
Work Orac						Rework	1		Skid-tube	Crosstube	]	Water Jet	Engineering
Part N	Vo.					Scrap			Machining	Small Fab	Pro	d. Eng. Coor.	Quality
						Use-as-is			noforming	Finishing	4	e/Packaging	Other
NCR N	No.					Work Order Update			Large Fab	Composite		Supplier	
-							•						
Root					Descri	ption of work order update	Į.	nitial		tion	Sign &		
Cause		Date	Step	Qty	(	or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data													
Equip/Tooling	Ш												
Operator .							l						
Material	Н												
Setup	Н			İ									
Other	Н												
Process	$\vdash$												
Supplier Training	Н			}									
Unapproved	$\vdash$												
Onapproved	ш		ł	L	<u> </u>	F	AUL	T CATE	GORY		L		<u></u>
Landi	ng G	Gear				General		<u> </u>				· · · · · · · · · · · · · · · · · · ·	
	lacksquare	Bending				Bend		Grain			Ovalized		Pressure/Forced
		Centre No	ot Conce	ntric to	o/s	BOM/Route		Hardwa	ire		Over/Under	tolerance	Temperature/Cure
		Cracks Broken/Damaged						Inspect	ion Incomplete		Part Incorre	ct [	Weld
		Crushed/	Crimped			Burrs		Instruct	ions Incomplete/	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	Cuffs					Contamination		Mainte	enance		Part Moved		
Heat Treat						Countersink		Mislabe	eled		Positioned V		<del></del>
	Ш	Inspectio		Tube		Cut Too Short		Misread	t		Power Loss/	Surge	Other
	Ш	Ripples in			L	Drill Holes	Offset					· · · · · · · · · · · · · · · · · · ·	
<u> </u>	Torque Waves in Extrusion Drawing							Out of 0	Calibration				

Out of Sequence


Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Finish

Folio




										DQA:	Date	:			
NCR: Y	es / No				WORK ORDER NON-	-COI	NFORI	MANCE / UP	DATE						
										QA Closed:	Date				
Work Orde	ř:				DISPOSITION		AGAINST DEPARTMENT/PROCESS								
Part N NCR N	o		- No		Scrap Machining Sm. Use-as-is Thermoforming Fir			Crosstube Small Fab Finishing Composite	<b>⊣</b>	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other				
Root				Desci	ription of work order update		Initial	Act	tion	Sign &		1.			
Cause	Date	Step	Qty		or Non-conformance	Cr	nief Eng	Descr	ription	Date	Verification	QC Inspector			
oc/Data															
quip/Tooling		1				1									
perator															
/laterial						1									
etup	·														
Other						1									
rocess		1				i		ĺ							
upplier						ŀ									
raining		•		·							·				
Inapproved										<u> </u>					
						FAUL	T CATE	GORY							
Landin	g Gear			-	General		-		_	_	<del></del> -	<del></del>			
L	Bending			Ĺ	Bend		Grain			Ovalized	_	Pressure/Forced			
	Centre N	ot Conce	ntric to (	o/s	BOM/Route	<u> </u>	Hardwa	re	_	Over/Under	tolerance	Temperature/Cure			
<u>l</u>	Cracks			<u> </u>	Broken/Damaged		Inspect	ion Incomplete	_	Part Incorre	ct _	Weld			
	Crushed,	hed/Crimped Burrs				_	-	ions Incomplete/U	Unclear	Part Lost/Mi	issing	Wrong Stock Pulled			
	Cuffs Contamination					Mainte	nance		Part Moved						
	Heat Treat Countersink						Mislabe	led		Positioned V	· -	_			
Ĺ	Inspection Strip in Tube Cut Too Short						Misread Power Loss/Surge Other					Other			
	Ripples in	n Bend			Drill Holes	Offset									
	Torque V	Vaves in E	extrusio	n [	Drawing		Out of 0	Calibration							
	Turning	Sequence		<b>.</b>	Finish		Out of	Sequence							

**Outside Dimensions** 

Wave/Twist in Tube

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



											DQA:	Date:			
NCR:	es /	' No				WORK ORDER NON-C	OI	NFORM	MANCE / UPDATE		QA Closed:	Date:			
Work Orde						DISPOSITION			AGAINST DEPARTMENT/PROCESS						
Part No.  NCR No.						Rework Scrap Use-as-is Work Order Update	Scrap Machining Small Fab Use-as-is Thermoforming Finishing			nall Fab nishing		Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other		
Root					Descri	ption of work order update	П	nitial	Action		Sign &				
Cause		Date	Step	Qty	,	or Non-conformance	Ch	ief Eng	Description		Date	Verification	QC Inspector		
Doc/Data															
Equip/Tooling	П				1										
Operator	$\Box$			<u> </u>	•										
Material	H						•								
Setup	Н														
Other	Н														
Process	П			ļ											
Supplier	П														
Training	П														
Unapproved															
						F.	AUL	T CATE	GORY						
Landi	ng Ge	ar				General		_			•		<b>-</b>		
	В	ending				Bend		Grain			Ovalized		Pressure/Forced		
	Пс	entre No	t Concer	ntric to	o/s	BOM/Route		Hardwa	re		Over/Under	tolerance	Temperature/Cure		
Cracks						Broken/Damaged		Inspecti	on Incomplete		Part Incorred	ct	Weld		
	Crushed/Crimped					Burrs		Instruct	ions Incomplete/Unclear	. 🗔	Part Lost/Mi	ssing	Wrong Stock Pulled		
ļ	Cuffs					Contamination		Maintenance			Part Moved		-		
	П⊦	leat Trea	t			Countersink		Mislabe	led		Positioned V	Vrong			

Misread Offset

Out of Calibration
Out of Sequence

Outside Dimensions

Other

Power Loss/Surge

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Inspection Strip in Tube

Torque Waves in Extrusion


Cut Too Short

Drill Holes

Drawing

Finish Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



									DQA:	Date:	. * `	
NCR: Ye	es / No			PDATE	QA Closed:	Date:	>					
Work Ordei	÷.		;		DISPOSITION		AGAINST DEPARTMENT/PROCESS					
Part No					Rework Scrap Use-as-is Work Order Update	The	Skid-tube Crosstube  Machining Small Fab  Thermoforming Finishing  Large Fab Composite			Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other	
Root		Description of work order update Initial Action										
Cause	Date	Step	Qty		or Non-conformance	Chief Er	ng Des	cription	Date	Verification	QC Inspector	
occ/Data quip/Tooling Operator Material Setup Other Process Supplier Fraining Unapproved												
		•				FAULT CA	TEGORY				,	
Landin	Bending Centre Not Concentric to O/S Cracks Crushed/Crimped Cuffs				General Bend BOM/Route Broken/Damaged Burrs Contamination	n ware ection Incomplete uctions Incomplete ntenance	/Unclear	Ovalized Over/Under Part Incorre Part Lost/M Part Moved	ct	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled		
-	Heat Trea	n Strip in	Tube		Countersink Cut Too Short	Misre			Positioned V Power Loss/		Other	
1	Ripples in			<u> </u>	Drill Holes	Offse	100					
}	Torque Waves in Extrusion Drawing  Turning Sequence Finish						Out of Calibration Out of Sequence					

Outside Dimensions

Wave/Twist in Tube

Folio